

HABS  
SC  
10-CHAR  
162-

# HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

### Addendum to:

Glebe House (Bishop Robert Smith House)  
6 Glebe Street  
Charleston  
Charleston County  
South Carolina

HABS No. SC-261

Photos SC-261-1 thru SC-261-4 were previously transmitted to the Library of Congress. The photos below were taken in August 1978 for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

- SC-261-5      SOUTH (FRONT) ELEVATION
- SC-261-6      NORTH (REAR) ELEVATION
- SC-261-7      WEST SIDE
- SC-261-8      EAST SIDE
- SC-261-9      STAIRS TO MAIN ENTRY, SOUTH (FRONT) ELEVATION
- SC-261-10     MAIN ENTRY, SOUTH (FRONT) ELEVATION.  
Door case is replacement of original.
- SC-261-11     FIRST FLOOR HALL LOOKING SOUTH
- SC-261-12     FIRST FLOOR HALL LOOKING NORTH
- SC-261-13     FIRST FLOOR, SOUTHWEST ROOM, EAST WALL  
Paneling is typical in house, except first floor northeast room.
- SC-261-14     FIRST FLOOR, SOUTHWEST ROOM, NORTH WALL
- SC-261-15     FIRST FLOOR, SOUTHWEST ROOM, WEST WALL.  
Windows and interior shutters typical in house
- SC-261-16     FIRST FLOOR, NORTHEAST ROOM, SOUTH WALL
- SC-261-17     TYPICAL FIRST FLOOR MANTLE (except northeast room)
- SC-261-18     TYPICAL FIRST FLOOR AND SECOND FLOOR HALL CORNICE

(continued)

GLEBE HOUSE  
Index To Photographs  
HABS No. SC-261 (page 2)

- SC-261-19 SECOND FLOOR, SOUTHEAST ROOM, NORTH WALL
- SC-261-20 SECOND FLOOR, SOUTHEAST ROOM: **CORNICE DETAIL**  
Typical for all second floor rooms except hall.
- SC-261-21 TYPICAL SECOND FLOOR MANTLE